


864385



A NOTE ADDED 7/3 BY 1-7731
 B 864436, 864459, 864775 56 1-28-31
 C NOTE ADDED C-5090 J.K. R.H. 3-25-31
 D E₂ ADDED LSK 4-8-31
 E 1/64 55 5-5-31
 F NOTE REVISED RSR 6-12-31
 G 865000 ADDED C-5230 J.B. 5-13-31
 H 864776 C-8129 R.H. 1-6-36
 J SUBSTITUTION 864569 R.H. 1-6-36
 K 864253 C-7239 R.H. 1-6-36
 L 864720 C-6271 R.H. 1-6-36
 M 864569 C-9659 R.H. 1-3-38

INNER TUBE MUST BE CONCENTRIC
 WITH OUTER TUBE WITHIN
 1/64 AND INNER TUBE MUST ALSO BE
 1/32" OVER 1/64 OUT OF ROUND

TO APPEAR
 180° FROM SEAM

CRIMP ALL AROUND

A SPRAY FILTER ELEMENT WITH OIL

B CLAMP 1526537 TO BE SHIPPED SEPARATELY

SPRAY ALL EXPOSED PARTS
 WITH BLACK DUCO - #6 FINISH

FEB 20 1933
 DISCONTINUED

A-3157
 864244

APPROVED
 Only
 Jimmy John

AIR CLEANER-SILENCER ASSEMBLY

SEE DETAILS

SEE NOTE

864385